BIL SOLUTIONS
bilsolutions.co.uk

CHECKLIST

Radiation detector maintenance checklist

- [ ] Wipe the housing with a damp lint-free cloth after each use
- [ ] Inspect the detector window for cracks, punctures or dirt
- [ ] Check battery contacts monthly for corrosion or leakage
- [ ] Remove batteries if storing the detector for more than a month
- [ ] Verify response against a check source before and after storage
- [ ] Store the detector in a cool, dry location away from temperature extremes
- [ ] Fit protective caps over thin windows during transport
- [ ] Arrange annual calibration verification through a qualified service
- [ ] Use a padded case with foam inserts for all transport